SAFETY ALERT



"Sharing incident learnings amongst ASI member companies"

"A vision of a safer steel industry"

Number: SA0027

Subject: Over filling of forklift gas bottle

Date May 2007

Incident:

Forklift operator was refilling gas bottle on forklift when gas started to rush out of the conection between the gas bottle entry valve and supply gas tank refilling hose, which resulted in operator being hit in face and arms with gas.

Upon Investigation it was found that the release valve on the bottle, which releases small burst of gas to indicate to the operator that bottle is full, was either faulty or had not been opened prior to refilling, causing operator to overfill bottle.

Release valve





Key Lessons:

• Ensure all operators are aware of the refilling procedures and to regularly assess new and safer alternatives on the market.

Recommendations: (maximum of 3)

- Have all standard (relief valve) gas bottles changed to <u>afl</u> (auto fill limiter) gas bottles to reduce human error factor when refilling.
- Ensure that all forklift operators are trained in the correct refilling procedures.

For further information please contact **Ian Cairns** – National Safety Group Co-ordinator: Tel: (03) 9694 4499; Fax (03) 9694 4498; email - <u>ianc@steel.org.au</u>

*** Safety Alerts are distributed by Australian Steel Institute as general information ONLY and are not intended as specific recommendations or advice ***