

SAFETY ALERT




AUSTRALIAN STEEL INSTITUTE
SAFETY GROUP

"Sharing incident learnings amongst ASI member companies"

"A vision of a safer steel industry"

Number:	SA0009
Subject:	Loss of load
Date :	May 2005

Incident: Loss of load under braking @ 50kph approximately



Key Lessons: (maximum of 3)

- Load restraint
- Driver awareness including distance from vehicle
- What if the van was a passenger vehicle/family car

Recommendations: (maximum of 3)

- Customers picking up, need to understand and use proper load restraint
- Covered steel packs are no guarantee that product is restrained appropriately
- Conduct load restraint audits at regular intervals

For further information please contact **Ian Cairns** – National Safety Group Co-ordinator:
Tel: (03) 9694 4499; Fax (03) 9694 4498; email - ianc@steel.org.au

*** Safety Alerts are distributed by Australian Steel Institute as general information ONLY and are not intended as specific recommendations or advice ***