

# Contents

<b>List of Figures</b>	<b>v</b>
<b>List of Tables</b>	<b>vii</b>
<b>1. Welded Connection Detailing</b> .....	<b>1</b>
1.2. Weld Preparation Details .....	5
1.3. Butt Weld Preparations .....	13
1.4. Standardised and Prequalified Weld Preparations .....	17
1.5. Joint Preparations at Skewed Angles .....	17
1.6. Common Connections .....	19
1.7. From Design to Manufacture .....	22
1.8. References .....	24
<b>2. Fatigue of Steel Structures</b> .....	<b>25</b>
2.1. Fatigue of Polished Samples .....	26
2.2. Fatigue Tests of Real Structures .....	26
2.3. Fatigue Design using AS 4100 .....	28
2.4. Structural Detail Categories .....	31
2.5. Factors Affecting Fatigue Life .....	37
2.6. Designing to Improve Fatigue Life .....	39
2.7. Treatments to Improve Fatigue Life .....	39
2.8. References .....	41
<b>3. Column and Beam Structures</b> .....	<b>42</b>
3.1. Introduction .....	42
3.2. Columns and Beams .....	42
3.3. Rigid and Flexible Connections .....	46
3.4. Welded Connections .....	47
3.5. Trusses .....	54
3.6. Erection .....	55
3.7. References .....	57
<b>4. Tubular Structures</b> .....	<b>58</b>
4.1. Tubular Material .....	58
4.2. Bend-forming of CHS, SHS and RHS .....	59
4.3. Forming of Tube from Plate .....	60
4.4. Weld Joint Designs .....	60
4.5. Welding and Inspection of Tubular Joints .....	67
4.6. References .....	68

<b>5. Storage and Processing Containers</b> .....	<b>69</b>
5.1. Pressure Vessels .....	69
5.2. Design of Tanks and Bins .....	69
5.3. Manufacture of pressure vessels .....	70
5.4. Manufacture of flat bottomed tanks .....	70
5.5. References .....	76
<b>6. Residual Stress and Distortion</b> .....	<b>77</b>
6.1. Residual Stress From a Thermal Gradient .....	77
6.2. Residual stress in welds .....	79
6.3. Consequences of residual and reaction Stress .....	80
6.4. Measurement of Residual Stress .....	82
6.5. Reduction of Residual Stress .....	84
6.6. Distortion and its Control .....	85
6.7. References .....	89
<b>7. Inspection and Testing</b> .....	<b>90</b>
7.1. Flaws, Non-Conformities and Defects .....	90
7.2. Inspection Integrity .....	90
7.3. Management of Inspections .....	91
7.4. Level of Inspection .....	92
7.5. Visual Inspection .....	94
7.6. Pre-welding Inspection .....	94
7.7. Liquid Penetrant Inspection .....	95
7.8. Magnetic Particle Inspection .....	97
7.9. Radiography .....	102
7.10. Ultrasonic Inspection .....	107
7.11. Proof Loading Tests .....	117
7.12. Other Techniques .....	119
7.13. References .....	122
<b>8. Management of Fabrication Quality</b> .....	<b>123</b>
8.1. Aims of Quality Management .....	123
8.2. Appropriate Level of Quality Management .....	123
8.3. Quality Assurance to ISO 9000 .....	125
8.4. AS / NZS / ISO 3834 Quality Requirements for Welding .....	127
8.5. Design and Project Management .....	129
8.6. Inspection and Test Plan (ITP) .....	131
8.7. Process Instructions .....	131
8.8. Welding Procedures .....	133
8.9. Welding Personnel .....	135
8.10. Fabrication Inspection .....	138
8.11. Identification and Tracability .....	138
8.12. Documentation .....	141
8.13. References .....	141
8.14. Examples of Quality Assurance Forms .....	141